



HANSA

Installation and maintenance guide



4-9



10-11




12-19



20-22



22-25




26-29



30

4417 0120


I (ISO 3822)
EN1112
50 - 500 kPa
0.20 l/s (300 kPa w/Controller)
max. +65°C



mpi.hansa.com/44170120

4417 0220



I (ISO 3822)
EN1112
50 - 500 kPa
0.20 l/s (300 kPa w/Controller)
max. +65°C





mpi.hansa.com/44170220

4413 0200



I (ISO 3822)
EN1112
50 - 500 kPa
max. +65°C



mpi.hansa.com/44130200







Max 65°C





①



cleaning.hansa.com